It is our belief that if reasonable precautions and care are taken in the use of the device. The device should not experience physical damage

HP Chromebook G5 Replacement Parts

Total Loss - \$240 •Screen - \$75 •Keyboard - \$65 TouchPad - \$60 Charger Port - \$60 ·Chassis - \$65 •Screen Lid - \$65 Keyboard Bezel - \$50 Damaged Ports - \$145 Charger - \$30